

FIG. 1






FIG. 2



09907368-071701

FIG. 3



T04T40"89E40660

FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8






FIG. 9



09907368-07101

FIG. 10



T04720-89E/0660

FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15

HLR			
N	SUBSCRIBER'S NUMBER	LOCATION IDENTIFICATION NUMBER WITHIN SERVICE AREA	
1	09015151515	LA-1	
2	09026262626	LA-2	
:	:	:	
HLR FOR PHS TERMINAL			
N	SUBSCRIBER'S NUMBER	IMT SUBSCRIBER'S NUMBER	LOCATION IDENTIFICATION NUMBER WITHIN SERVICE AREA
1	07012345678	0903737373	LA-3
2	07012121212	0904848484	LA-2
:	:	:	:
HLR FOR PDC TERMINAL			
N	SUBSCRIBER'S NUMBER	IMT SUBSCRIBER'S NUMBER	LOCATION IDENTIFICATION NUMBER WITHIN SERVICE AREA
1	09098989898	0905959595	LA-2
2	09087654321	0903737373	LA-3
:	:	:	:

FIG. 16

N	SUBSCRIBER'S NUMBER	NETWORK IDENTIFICATION NUMBER WITHIN SERVICE AREA	LOCATION IDENTIFICATION NUMBER WITHIN SERVICE AREA
1	07013131313	—	PLA-1
2	07024242424	—	PLA-2
3	07035353535	—	PLA-3
4	07046464646	—	PLA-2
:	:	:	:
n	07012345678	ITM2000	—
:	:	:	:

FIG. 17




FIG. 18

